Fig.1




Fig.2




Fig.3





Fig.4






Fig.6




Fig.7

DEPENDENCY OF WARM-UP TIME (IDLING) ON PRESSURIZING ROLLER




Fig.8




Fig.9




Fig.10A




Fig.10B

